

INTERIM CHANGE FORM

179923

Change No. RAR-038

Document No. 400

Section No. 8.1

Page No. N/A

Revision No. 2

Requirement: RAR Scoping and Planning Document#400, Site-Specific Health & Safety Plan for Kerr-McGee - Residential Areas Site, Section 8.1

Change: Replace Section 8.1 with the updated attachment.

Effective Date:

8/21/98

Approval:


OFFSITE PROJECT MANAGER

8/28/98
DATE

8.0 PROTECTIVE EQUIPMENT

8.1 Job Task Specific Envirocon/Subcontractors Personal Protective Equipment Assignment

JOB TASK/LOCATION	RESPIRATOR LEVELS/EQUIPMENT	PROTECTIVE CLOTHING	SPECIAL SAFETY EQUIPMENT
Any Position Upgraded to Level C	Level C full-face respirator with HEPA cartridges	cotton coveralls work gloves boot covers	leather steel toe boots hard hats safety glasses hearing protection
Tree Removal (subs)	Level D	work gloves fall protection equipment	leather steel toe boots hard hats safety glasses hearing protection
Shrub Removal (subs)	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection
Selective Demolition with Hand Tools (Envirocon)*	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Selective Demolition with Gas or Diesel Powered Equip (Envirocon)*	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Excavation Equipment Operator*	Level D	work gloves boot covers	leather steel toe boots hard hats safety glasses hearing protection safety vests

JOB TASK/LOCATION	RESPIRATOR LEVELS/EQUIPMENT	PROTECTIVE CLOTHING	SPECIAL SAFETY EQUIPMENT
Excavation Laborer*	Level D	work gloves boot covers	leather steel toe boots hard hats safety glasses hearing protection safety vests
Dumptruck Driver	Level D		leather steel toe boots hard hats safety glasses hearing protection safety vests
Maintain Dump Pad (laborer/sweep)	Level D	cotton coveralls work gloves boot covers	leather steel toe boots hard hats safety glasses hearing protection safety vests
Backfill Equipment Operator	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vest
Backfill Laborer	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Concrete Forming and Pouring	Level D	protective gloves such as rubber or nitrile for pouring. work gloves for forming.	leather steel toe boots hard hats safety glasses hearing protection safety vests

JOB TASK/LOCATION	RESPIRATOR LEVELS/EQUIPMENT	PROTECTIVE CLOTHING	SPECIAL SAFETY EQUIPMENT
Pressure Washing	Level D	rain gear or water resistant material. boot covers face shield	leather steel toe boots hard hats safety glasses hearing protection safety vests
Remove/Stockpile Asphalt*	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Asphalt Paving (subs)	Level D		leather steel toe boots hard hats safety glasses hearing protection
Septic Tank Installers Laborer and Operator (subs)	Level D		leather steel toe boots hard hats safety glasses hearing protection
Landscapers: plant sod, grass, seed, trees, shrubs, operating weed wacker, working around heavy equipment	Level D		leather steel toe boots hard hats safety glasses hearing protection safety vests
Landscape borders, covering, interlocking block walls, block pavers	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests

JOB TASK/LOCATION	RESPIRATOR LEVELS/EQUIPMENT	PROTECTIVE CLOTHING	SPECIAL SAFETY EQUIPMENT
Install Timber Retaining Walls	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Install Wood Decks	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection safety vests
Install Wood Decks, Working with Rotating Power Tools	Level D	work gloves	leather steel toe boots hard hats safety glasses hearing protection

*Cotton coveralls or other full body protective suits will be required when gamma levels reach or exceed readings corresponding to an average concentration of 30pCi/g as determined by the Health Physics Department. When gamma levels are less than readings corresponding to an average concentration of 30pCi/g, coveralls will be optional and available to any employee who chooses to wear them in the Exclusion Zone.

Under certain field conditions, the SHSO, PM, or HP may require coveralls to be worn when gamma levels are less than readings corresponding to an average concentration of 30pCi/g (i.e. kneeling on contaminated ground, working in ditches, hand excavating crawl spaces and activities where contaminated soil may be grounded into personal clothing or the skin.